# **Balloon Federation of America**

An Air Sport Organization of the NAA

P.O. Box 400 Indianola, Iowa 50125 515/961-8809 515/961-3537 (fax) e-mail: BFAOffice@aol.com

Federal Aviation Administration Office of the Chief Council

Attention: Rules Docket (AGC – 10) 800 Independence Avenue SW

Washington, DC 20591



Pursuant to Section 11.25 of the Federal Aviation Regulation (FAR), the Harcon Federation of America (FAA) hereby petitions the Federal Aviation Administration (FAA) for exemption from FAR Sections 91 119 (b) and (c) to the extent necessary to permit the BFA to concluct a sponsoring study of the increase in safety to persons and property on the ground by allowing balloon pilots to fly at lower altitudes. (See Appendix A, BFA Safety Study.) The BFA is a 501(c)3 educational organization with 4,000 members founded in 1967 for the purpose of enhancing safety and promoting the sport of ballooning.

Under this study, balloons would be permitted to fly at an altitude sufficient to ensure the safe operation of the aircraft with respect to persons, vessels, vehicles or structures on the surface, rather than being restricted to an altitude of 1,000 feet above the highest obstacle within a horizontal radius of 2,000 feet in congested areas, and 500 feet over other than congested areas.

The BFA believes such an exemption would greatly enhance the safety of balloon flight from the standpoint of persons and property on the ground, and expects to prove such in the proposed study.

## NATURE AND EXTENT OF RELIEF

Implementation of the BFA study will require exemptions to the following sections of the FARs: 91.119(b) and 91.119(c)

FAR 91.119(b) states, in pertinent part, "Except when necessary for takeoff or landing, no person may operate an aircraft below the following altitudes: (b) Over congested areas. Over any congested area of a city, town or settlement, or over any open air assembly of persons, an altitude of 1,000 feet above the highest obstacle within a horizontal radius of 2,000 feet of the aircraft.

The relief requested is from this entire subsection.

FAR 91.119(c) states, in pertinent part, "Except when necessary for takeoff or landing, not person may operate an aircraft below the following altitudes: c) Over other than confeeted areas. An altitude of 500 feet above the surface, except over open water or sparsely concluded areas. In those cases, the aircraft may not be operated closer than 500 feet to any person, vessel, vehicle or structure.

The relief requested is from this entire subsection.

## AIRCRAFT AND PERSONS COVERED BY THE EXEMPTION

- 1. U.S. registered aircraft and foreign registered aircraft operated by U.S. certificated pilots. The following aircraft are proposed to be covered by the exemption:
- a. U.S. registered lighter than air free balloons with airborne heater
- b. U.S. registered lighter than air free balloons without airborne heater
- c. Foreign registered lighter than air free balloons with or without airborne heater, provided they carry an airworthiness certificate from the country of registration, and are operated by a pilot covered by Paragraph 2 below.

#### 2. BFA member pilots

In order to monitor and control the study, only BFA member pilots will participate. This will allow tracking of the pilots in the study, and will ensure that participating pilots receive the continuous flow of educational and safety publications produced on a monthly basis by the BFA. In addition, BFA pilots receive the most complete listing of balloon safety seminar information in the country. The BFA will keep its pilots informed of the ongoing results of the study through monthly updates in BFA publications, and more immediate updates on the BFA web site, www.bfa.net.

Pilots covered by the Exemption must:

- a. carry a Private or Commercial airman's certificate, with a rating for lighter-than air free ballocns.
- b. be a current member in good standing of the Balloon Federation of America.

## **PUBLIC INTEREST**

1. Safety to persons or property on the surface

Granting of this petition for exemption to permit balloons to fly at any altitude sufficient to provide adequate clearance from persons and property on the surface is in the public interest for reasons of safety.

Unlike any other aircraft, balloons are aerostatic—pilots have only one method of horizontal directional control at their disposal—changing their altitude. As the table below clearly shows, wind direction on any given day normally changes even in increments of 100 feet or less. (For a more complete explanation of balloon flight characteristics, see Appendix B, How Balloons Fly.)

A recent study undertaken by meteoroligist Dr. Richard Clark, a professor at Millersville University, provides irrefutable proof that the majority of changes in wind direction occur with decreasing altitude. Most of these directional variations are found at altitudes below 1,000 feet, the majority below 500 feet.

Allowing balloon pilots to make use of these changes as they plan their flights and landings will enable pilots to enhance the safety of balloon flight to persons and property on the surface, and to passengers, by making full use of all levels of altitude, rather than just those above 500 or 1000 feet as the regulation now reads.

Additional operable altitudes provide additional opportunities to change or adjust horizontal direction. Therefor, a pilot has significantly increased opportunity to respond to changes in terrain and to maneuver away from persons or obstacles, thereby providing a safer landing.

Each year, more than 300 balloon events are conducted under an FAA waiver, which provides, in part, relief from the minimum altitude restrictions required by the above two subsections. A review of the accident investigation summaries posted by the NTSB since 1983 shows that the granting of this waiver has had no adverse effect on the accident statistics during balloon events. Since waivered events provide the only legal opportunity for balloon pilots to operate outside these restrictions, such data is highly instructive. The BFA Study aims to provide similar data pertaining to balloon operations outside the confines of balloon events; in other words; balloon flights conducted under standard, daily, non-event operating conditions.

#### 2. Safety to passengers

In the event of a burner failure, the ability to fly at a lower altitude enables the pilot to perform an emergency landing with much more control as to its location, greatly enhancing the safety to pilot and passengers. Such landings performed from high altitude have a far lower level of control.

## **EQUIVALENT LEVEL OF SAFETY**

The BFA's proposed study and requested exemptions will not merely provide an equivalent level of safety to perations under this present regulation, but will in fact, enhance safety. Operations under the exemption requested herein should enhance total air safety due to the enhanced level of maneuverability resulting from the exemption.

In a number of documented cases, lives could have been saved, injuries avoided and property left undamaged had balloon pilots been permitted to fly at lower altitudes and maneuver more accurately to a safe and appropriate landing site.

In summary, the BFA believes that our proposed study will prove that unrestricted altitudes will address this critical need for improved maneuverability, and result in increased safety for persons and property on the surface, as well as for passengers.

### **SUMMARY**

As required by FAR Section 11.25(d), a summary of the petition is as follows:

The Balloon Federation of America (BFA) petitions the Federal Aviation Administration for relief from the provisions of 14 CFR 91.119 (b) and (c) (minimum altitude requirements), to conduct a safety study. The requested relief will allow BFA member pilots to operate and maneuver at altitudes lower than those provided for in the rule. This relief from altitude restriction will improve the safety of balloon operations by increasing the maneuverability of the aircraft to the maximum extent permitted by prevailing weather conditions. It will also reduce the severity of accidents and incidents resulting from equipment failure by allowing pilots to land their aircraft as soon as safely possible.

Sundant Sundant

Charles Sundquist

President, Balloon Federation of America

# APPENDIX A—BFA SAFETY STUDY

The BFA proposes a three-year study to evaluate the safety enhancements provided by an exemption from FAR 91.119(b) and FAR 91.119(c). We believe such a study will provide informative and useful data in an effort to re-assess the regulation as it applies to lighter-than-air flight.

## AIRCRAFT AND PERSONS COVERED BY THE EXEMPTION

- 1. U.S. registered aircraft and foreign registered aircraft operated by U.S. certificated pilots. The following aircraft are proposed to be covered by the exemption:
  - a. U.S. registered lighter than air free balloons with airborne heater
  - b. U.S. registered lighter than air free balloons without airborne heater
  - c. Foreign registered lighter than air free balloons with or without airborne heater, provided they care an airworthiness certificate from the country of registration, and are operated by a pilot covered by Paragraph 2 below.

## 2. BFA member pilots

In order to monitor and control the study, only BFA member pilots will participate. This will allow tracking of the pilots in the study, and will ensure that participating pilots receive the continuous flow of educational and safety publications produced on a monthly basis by the BFA. In addition, BFA pilots receive the most complete listing of balloon safety seminar information in the country. The BFA will keep its pilots informed of the ongoing results of the study through monthly updates in BFA publications, and more immediate updates on the BFA web site, www.bfa.net.

#### Pilots covered by the Exemption must:

- a. carry a Private or Commercial airman's certificate, with a rating for lighter-than air free balloons.
- b. be a current member in good standing of the Balloon Federation of America.

## **CURRENT WAIVER STRUCTURE FOR EVENTS**

Under the current regulatory structure, balloon event organizers and officials apply for waivers so that their pilots may be freed from the requirements of 91.119(b) and 91.119(c). These waivers are granted as a matter of course, more than 300 of them per year. Pilots participating in such events agree to abide by the waiver, which includes wording to make sure they don't fly so close to the ground as to endanger people or property on the surface.

A review of incidents and accidents\* involving lighter-than-air free balloons operating within the standard regulatory structure, and within waivered events, shows virtually no difference in the proportion of incidents and accidents per flight operation between waivered and non-waivered events and operations. There is a slight increase in safety in waivered events, but the difference is not statistically significant.

<sup>\*</sup> Taken from the NTSB Accident Synopses web site: www.ntsb.gov/aviation/months.htm

It is important to remember that waivers are issued primarily for balloon competition or airshowtype events. Non-waivered flight operations take place with far less congestion of aircraft, and enable the pilot to make even better use of an altitude exemption for maximizing flight safety in maneuvering the aircraft.

One BFA pilot, operating in Texas, obtained an individual waiver releasing him from the altitude restrictions of FAR 91.119 for the purpose of advertising. The pilot operated under the waiver for a period of two years, without incident.

Enabling pilots to assess and use everything at their disposal, especially the forces of nature which govern their direction of flight, enables those pilots to best ensure the safety of persons or property on the surface.

## **COLLECTION OF DATA**

The BFA will appoint a suitable party to collect and report data during the course of the study. This will include:

- · voluntary feedback from participating pilots
- · accident information from participating and non-participating pilots
- comments from FAA FSDOs (through a liaison designated by the FAA).

## **EVALUATION**

At the conclusion of the study, the BFA will be available to participate with the FAA in the evaluation of its results, with the goal of providing the safest possible regulatory environment for balloons.

## Appendix B-How Balloons Fly

Horizontal movement, or "steerage" in ballooning is a matter of finding air currents approximating the desired direction of flight.

Unlike other forms of aircraft, lighter than air free balloons have no direct horizontal directional control. The only means by which a pilot may change the direction of his aircraft is to change its vertical position in the air (altitude) by means of changing the relative buoyancy of the aircraft. This is done by adjusting the pressure within the balloon's envelope, either by changing its temperature (hot air balloon) or releasing ballast or gas (gas balloon).

Balloon pilots learn to be ultra-sensitive to even 1- or 5-degree changes in wind direction, and to employ these changes as necessary for safe flight. Figure 1 below illustrates a typical wind speed and direction profile, both forecast and actual, during a balloon flight.

unch,	Flight:	and Recove	ery:	
Hat	DIF	3 <del>p</del> d	At left, actual readings taken fron	n an observation balloon approxima
FT	DEG	KTS	ly 2 hours before launch (at 0500	
				wear time was 0415 wear for
-	010		Rantoul, Illinois).	
298 488	919 9 <del>96</del>	11		
520	887	11 10	Relow forecast wind data for the	same location, during the flight peri
638	885			same tocation, auring the jugat peri
750	359	75140	od of 1200 to 1500 UTC.	
866	355	à.		
988	356	7 N	215 08/11/99 1200	2I5 08/11/99 1500
1999	355	s 70		
1219	354	75140	alt mb the wednesde spe	est up the mainstant
1320	359	ž 2	(ft) (°C) (kts)	(ft) (°C) (ks)
1440 1559	349 351	U:	669 990 19.7/17.80 343°/004	669 991 24.0/18.10 3497/004
1678	351	à	738 988 19.9/17.70 345%005	741 989 23.3/18.00 3479/004
1780	354	9	879 983 19.8/17.60 346°/006	883 984 22.8/17.90 3479/004
1900	347	ė	1093 975 19.8/17.40 351º/008	1099 977 22,2/17.70 348*/005
2010	346	3	1378 966 19.7/17.20 3564/009	1388 967 21.4/17.50 349°/005
	<b>.</b> .		1814 951 19.7/16.80 3589/010	1824 952 20.1/17.10 3519/005
H <sub>9</sub> t	Dir	Sed CTA	2254 936 19.5/16.30 358°/009	2264 937 18.9/16.30 356*/006
FT	DEB	KTS	2592 925 19.2/15.70 355*/009	2638 925 18.4/15.50 3569/006
			2700 922 19.1/15.50 3549/009	2710 923 18.3/15.30 356°/006
290	886	13	3156 907 18.4/14.50 349*/009	3163 908 17.8/14.30 3529/006
409	390	12	3615 892 17.8/13.20 342%010	3622 893 17.1/13.00 351//006
528	997	11	4081 877 17.0/11.60 335%011	4088 878 16.5/11.30 349*/007
638	904	9	4554 863 16.3/9.700 327%012	4560 864 15.9/9.300 344*/008
758	359	ž 1		
369 938	356	9500r		5007 850 15.5/7.000 339%010
1090	355 357	<b>7</b> . 5	5033 848 15.6/7,300 318%013	5039 849 15.5/6.800 3399/010
1210	354	i S	5518 833 14.9/4.600 3129/014	5528 834 15.0/4.000 336°/011
1320	356	8 <i>(</i> )	6010 819 14.3/1.700 3119/014	6020 820 14.7/1.000 3367/011
1440	356	0.2001 	6512 804 13.8/-1.10 314%015	6522 805 14.4/-1.90 3379/012
1550	223		7021 789 13.5/-4.00 320*/016	7034 790 14.3/-4.70 3387/012
1679	939	18	7539 775 13.4/-6.80 324°/017	7556 775 14.21-7.20 339%013
1780	359	9	<b>8068</b> 760 13.2/-9.40 328°/018	8084 761 13.8/-9.30 337°/014
1988	3 <b>5</b> 9 352	18 5	8602 745 12.9/-11.6 3289/018	8622 746 13.3/-11.1 333°/015
2018	302	7	9150 731 12.4/-13.6 325°/018	9173 731 12.6/-12.7 327/017

Figure 1

The left columns depict an actual theodolite reading taken by the onsite meteorologist at the U.S. National Hot Air Balloon Championship, the BFA's largest event, and given to pilots as part of their preflight briefing. Altitude is represented AGL.

The right columns are the forecast (GMT) for the same location during the flight window. Altitudes are represented MSL, with field elevation at 737 ft.

Both readings show how wind speed and/or direction can change to a degree clearly significant to balloonists, with very small changes in altitude...

These changes in direction play a critical role in the pilot's ability to avoid obstacles, particularly in the landing phase of the flight. Balloons rarely land at airports—such is beyond the operational capability of the aircraft. Therefor, a safe landing is largely dependent on the pilot's ability to assess the wind speed and direction at all altitudes, particularly those close to the ground, which the pilot must use for landing approach.

An added challenge to balloonists is the tendency of the wind directions at various altitudes to change slightly during flight, due to normal heating or cooling of the earth's surface, changing weather conditions, etc. Remember, just a one- or two-degree shift often makes the difference between making or missing an appropriate landing site. And such shifts can take place in very small altitudinal increments (sometimes 50 feet or less), particularly at lower altitudes.

A recent study undertaken by meteoroligist Dr. Richard Clark, a professor at Millersville University, provides irrefutable proof that the majority of changes in wind direction occur with decreasing altitude. Most of these directional variations are found at altitudes below 1,000 feet, the majority below 500 feet.

Enabling pilots to assess and use everything at their disposal, especially the forces of nature which govern their direction of flight, enables those pilots to best ensure the safety of persons or property on the surface.

Relief from altitude restrictions would enhance safety by enabling the pilot to plan and execute controlled, stabilized approaches at low altitude, utilizing time spent at lower altitudes to reasonably assess and respond to changes in speed and direction resulting from boundary-layer meteorological effects.

For example, the slight change in direction of surface air currents resulting from a body of water, plowed field, or mass of trees can be used to execute a precise approach to an appropriate landing site, if the pilot is able to utilize this slight change to "steer" to that landing site. These changes in direction or speed often occur only very close to the surface.

While the AIM reports adverse affects of microbursts on aircraft flying at low altitudes, and while microbursts as such are not easily detectable, the conditions which must be present in order to produce a microburst are clear. The study states that "...microbursts commonly occur within the heavy rain portion of thunderstorms, and in much weaker, benign appearing convective cells..."

Balloons are *never* intentionally flown in conditions favoring thunderstorms or microbursts. One of the first things a student balloon pilot learns in training is *never* to launch within 50 miles (or more, in some cases) of any convective activity, and always to ask for reports of such activity in the preflight weather briefing. In addition, the balloon pilot is always on the alert for convective activity forming during flight.

Freedom to fly at lower altitudes would enhance the safety to persons and property on the ground, to the pilot, and to passengers.

## APPENDIX C

# Summary of Available Data Concerning Altitude Restrictions and Their Effect on Balloon Operations As Reported by the Aviation Safety Reporting System in ASRS Directline, Issue Number 9

The overwhelming majority of ballooning mishaps occur during the landing phase. Equipment failure in this type of aircraft is rare, and multiple redundancies in system design usually enable the pilot to deal with any emergency in a safe and efficient manner.

A study of reports submitted to the Aviation Safety Reporting System, or ASRS, reveals that, quite frequently, pilots submit these reports as a result of having violated the provisions of FAIR 91.119. In fact, the largest number of these reports, 20% or more, specifically deal with low-altitude flight. Many of the other reporting reasons, such as landing in a residential area, power line contact, hard landings, and airspace violations, can reasonably be assumed to have been avoidable had the pilots been free to use wind at lower altitudes to "steer" their aircraft in a safer direction. A recent study undertaken by meteoroligist Dr. Richard Clark, a professor at Millersville University, provides irrefutable proof that the majority of changes in wind direction occur with decreasing altitude. Most of these directional variations are found at altitudes below 1,000 feet, the majority below 500 feet.

Below is a table showing the percentages for each category of reported incidents received by the ASRS. Multiple citations are possible within the same report, thus the combined total of percentages shown is greater than 100%.

Low-Altitude flight	20%
Power line contact	16%
Landing in residential areas	16%
High wind/hard landing	11%
Airspace violations	10%
Miscellaneous	10%
Ground incidents	9%
Mid-air collisions	8%
Ground personnel perceptions	7%
VFR in IMC	7%
Balloon in airplanes' airspace	6%
Livestock incidents	4%
Propane leak/fuel contamination	4%

When faced with changing weather situations, either increasing or decreasing wind, approaching inclement weather or darkness, it becomes ever more important for pilots to be able to use every reasonable means available to maneuver their craft to the safest possible landing.

Fully 60% of the above mentioned reports involved weather-related causes. Of these, 66% listed unforecast increasing winds as the problem. Others cited thermals, becoming becalmed, or VFR into IMC due to fog or fast-forming clouds underneath the balloons in flight.

In all of these scenarios, lower altitude provides the maximum degree of safety in balloon operation.

In a high wind scenario, a pilot is free to drop quickly into an available landing site, using all of its length for the horizontal drag that usually results in high winds. If the pilot is forced to make a landing approach from 1000 feet, the faster ground winds blow him off course before he can safely land. The solution is a high-vertical-speed descent, which is far more likely to cause injury and damage to passengers and property on the surface than a horizontal drag of any distance.

In the case of low or no wind, usually occurring just before sunset, the pilot of a balloon at low altitude is more able to drop a ground handling line to waiting crew to assist him into a suitable landing site. Before reaching that necessity, he would have been able to make use of lower-level winds to "steer" his balloon to a suitable location.

If a balloon pilot encounters thermals, the safe course of action is to climb out of the thermal, fly at altitude to a thermal-free area, then descend to a safe landing. Having reached a good landing site, however, the pilot must again use various wind directions at lower altitudes (in the boundary layers of wind just above the surface) to maneuver to a safe terminus.

Perhaps most important in the desirability of low altitude flight is the formation of fog or low clouds underneath the balloon. With the relatively low speed at which balloons fly, and the total visibility below that a pilot enjoys while standing in an open basket, the pilot can usually see the signs of low cloud of fog beginning to form. At this point, the safest thing for the pilot to do is to descend to just above the treetops, and utilize the first available landing site. From 1000 or even 500 feet, it's nearly impossible to see obstacles such as buildings or power lines.

In the NTSB's accident and incident database, one can easily separate incidents taking place within the structure of a balloon event or in general operating circumstances. The majority of such events operate under the standard waiver referred to above. The percentage of accidents occurring under this waiver is slightly lower than those occurring in non-waivered flight. While the difference is too small to point convincingly to waivered flight (and its accompanying relief from altitude restriction) being safer than non-waivered flight, it certainly is a clear indication that lower altitude does not, by itself, cause an increase in accidents or incidents.